

PROJECT PROFILE

PROJECT: Food Production Hall

LOCATION: Slovakia

THE PROBLEM

The internal walls and ceiling in this cheese production hall were in an extremely poor condition.

The surfaces were heavily contaminated with mould and immediate refurbishment was required to bring the hall up to acceptable hygiene standards.



THE SOLUTION



Using Thortex materials, our distributor, H & H Unikov were able to undertake a complete refurbishment of the cheese production hall walls and ceiling.

The Wall-Tech WB system offered the ideal solution. It is easy to apply and caused minimum disruption to normal work practices.

This coating system completely upgraded the wall and ceiling areas and will prevent the return of mould and bacteria to these surfaces in the future.