

## PROJECT PROFILE

**PROJECT:** Campa Biodiesel \_ Oil Industry  
**LOCATION:** Germany

### THE PROBLEM


This picture has been taken in a bio diesel factory in Ochsenfurt, Germany.

In order to produce the bio diesel, the manufacturer is using rape oil causing severe abrasion and damage to the factory floors.

After testing many floor coatings, Thortex was asked to do a trial, which was successful.



### THE SOLUTION



The floor surface was prepared by blast cleaning.

Floor-Tech SP Primer, a solvent free floor primer which offers excellent adhesion to concrete surface, was applied.

Two coats of Floor Tech HB, a high build ceramic enhanced solvent free floor coating was used to provide a high performance finish with good chemical and abrasion resistance.

In order to get a non-slip surface, HD Aggregate was incorporated into the system.

The customer was highly satisfied by the result.