



## PROJECT PROFILE

**PROJECT:** Anti-Slip Protection System for Steps

**LOCATION:** United Kingdom

### THE PROBLEM

The steps featured in the photograph form the main entrance to a client's offices and had become a safety hazard in wet and icy weather. An anti-slip protection system was sought.



### THE SOLUTION



All dirt deposits and other contamination were removed from the concrete; the step nosings were then abraded. These abraded areas were then coated with Grip-Tech. This system is a solvent-free epoxy coating, which has been combined with an abrasion resistant aggregate. It has been specifically designed for use as a slip-deterrent safety system.

The client has reported no further accidents since the application.